Equipment Workshop Findings

Assessment Record

Operator: Silverleaf Ambulatory Care LLC. Location: 1607 Alder Court, Suite C.

Claim CLM-26-822494; examination date 2026-09-02.

Condition and Repairability

The utility compressor and vacuum motor beneath the dispensary run have wet control housings. The repair technician measured failed insulation after drying and documented matching replacement capacities. The operator's asset register contains both units; disposal is included in the vendor scope.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.