Plumbing Attendance Sheet

Service Record

Customer: Silverleaf Ambulatory Care LLC. Claim reference: CLM-26-822494.

Visit: 2026-08-24. Address: 1607 Alder Court, Suite C.

Cause Assessment

A push-fit connection above the dispensary released from its seat. The plumber found the retaining collar displaced and the branch still pressurized. The connection was replaced and tested before the ceiling opening was covered temporarily. The work order includes the connection and test, not the downstream finishes.

Work Notes

The service ticket was closed on 2026-08-24 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.