

MRPL REFINERY - ROTATING EQUIPMENT LOG

Equipment ID: BLR-302

Boiler Feed Water Pump Inspection

Vibration Velocity: 2.3 mm/s RMS

Bearing Temperature: 68.5 C

Date: 2026-09-05

Inspector: Mechanical Maintenance Team A