

MRPL REFINERY MECHANICAL INTEGRITY SURVEY

Section 1: Rotating Machinery Overview

| Equipment Tag | Parameter | Velocity RMS | Temp | Date | Status |

|---|---|---|---|---|---|

| TRB-1105 | Turbine Drive | 5.8 mm/s | 78.5 C | 2026-09-05 | Zone C Alert |

| PMP-204 | Booster Pump | 9.2 mm/s | 88.0 C | 2026-09-05 | Zone D Critical |

Section 2: Detailed Recommendations for PMP-204

Vibration exceeds allowable limits. Immediate lubrication replenishment required.