

Generated: 02 May 2026, 05:52 PM
Report ID: RPT-MTR_0020-20260502

Meter Details

Meter ID:	MTR_0020
Feeder Zone:	Zone_1
Signals Triggered:	3
Risk Level:	HIGH

Decision Support Analysis

- WHY:**
- usage is far below peer cluster + unusual evening dip pattern detected + feeder-meter energy imbalance
- HOW SERIOUS:**
- High risk (3 signals)
- WHAT TO DO:**
- Immediate physical inspection recommended

