Home

Crashes

Admin **▼**

My Account ▼

Print / PDF




English -

Crash Storyline

Crash ID: 182471 Trip ID: 1468197334 Crash Time: 8/30/2020, 15:08:30 Driver: Said Crash Location: TX-8 Beltway, Houston, TX 77067, USA Confirmed: - -

Crash Description The driver was traveling South along North Sam Houston Parkway West at 58 km/h at

15:08:28 on 2020/08/30. The driver then began braking prior to the impact. At 15:08:30 a collision occurred on the right side of the vehicle while the vehicle was traveling at 12 km/h. The collision event ended at 15:08:32 when the vehicle reached a speed of 1 km/h. The driver continued driving after the crash event toward their destination.



Notes


Crash Info

Disclaimer

Driver Info

Precipitation: None Wind: 13 km/h E Wind Gust: 24 km/h Visibility: 16 km Daytime: Yes Sun Facing Driver: No

Observed: 03:10 PM



Г٦


Confirmed None


Vehicle Info

Level of Damage Unknown Unknown **Bodily Injury** Edit Edit

App Info

Number of Impacts:	
Speed Before Crash:	58 km/h
Speed at Impact:	12 km/h
Speed After Crash:	1 km/h
Delta-V:	-57 km/h
Mean Acceleration:	-0.41 g
Heading at Impact:	South
Crash Duration:	4.4s
Мар	





Home

Driver Locations

Companies

Mobile Apps

Fleets

The second second second second

Teams

Drivers

Vehicles

Trips -

Geofences -

Crashes -

Cidolioo

Impacts

Crashes

Incidents

Incident Framework

Internal Tools -

Admin -

Firmware -

My Account ▼

Filters: All Companies ▼ All Fleets ▼
All Teams

Hi izzat.jarudi!

English ▼

America/Chicago | HELP | LOGOUT

Print / PDF

Edit




Crash Storyline


Crash ID: 2929 Trip ID: 1102223 Driver: rrjmhn Crash Time: 5/29/2020, 17:03:57

Crash Location: I-84, Sturbridge, MA 01566, USA Confirmed: Yes


Crash Description The driver was traveling South along Wilbur Cross Highway at 81 mph at 17:03:55 on


2020/05/29. The driver then began braking prior to the impact. At 17:03:57 a collision occurred on the rear side of the vehicle while the vehicle was traveling at 66 mph. The driver was speeding prior to the impact. The collision event ended at 17:04:04 when the vehicle reached a speed of 15 mph. The airbag deployed at 17:04:04. The driver did not continue on their trip after the crash event.






Edit





Disclaimer



7:44:58

7:45:00

7:45:02

7:45:04

7:45:06

7:45:08

7:45:10

7:45:12

Home

<u>Crashes</u>

Admin **▼**

7:44:46

7:44:48

7:44:50

7:44:52

7:44:54

7:44:56