ra calibration board - 10 x 7 squares, 25 mm each (9 x 6 inner corners)

/ Actual size (NOT Fit to page). Glue flat on stiff card or board. Keep matte, no gloss.





v must measure exactly 100 mm with a ruler. Measure one square: it must be 25.0 mm.

not 25.0 mm, tell Claude the measured size - it is used in the calibration.