



Initial Scene Sketch and Event Timeline

A starter-stage orientation record combining only the reported scene relationships and event sequence. Exact distances are not asserted.

Document ID	Incident	Record type	Status
R3-START-002	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled



Known sequence from preliminary reporting; exact transition mechanism remains open



Time anchors

Time / interval	Reported event	Precision	Status
Previous shift	Work rolls and top and bottom backup rolls removed for outage work.	Shift-level only	Historical source fact
Previous shift	Top backup roll balance left isolated raised; B hydraulics shut off and bled.	Sequence within shift not established	Historical source fact
Morning of 10/14	Several contractor employees worked in the R3 pit.	Names and exact times not in starter record	Historical source fact
Approx. 1:03 PM	Carrier beam fell into pit; two nearby contractor employees witnessed the event.	Narrative time	Historical source fact
Approx. 1:05 PM	Structured event-time field in historical record.	Two-minute difference from narrative	Open / reconcile
After event	Work stopped and area red-flagged for investigation.	Exact time not provided	Historical source fact

Scene limits

- The yoke and link seating surfaces are not visible in this sketch.
- The witnesses' exact sight lines are not established.
- No pre-event photograph is included.
- The fall path is reported, not reconstructed.