

Hydraulic Status and Bleed Verification

A synthetic field-data summary distinguishing recorded pressure state from mechanical support state.

Document ID	Incident	Record type	Status
R3-EV-011	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Recorded readings

Point / source	Reading or state	Time	Limitation	Status
B-system supply gauge	0 psi after bleed	10/14 - 12:28 AM	Local gauge accuracy not independently calibrated for investigation.	Synthetic scenario fact
B-system return / bleed	Bleed path recorded open	10/14 - 12:28 AM	Exact trapped volumes not mapped in field record.	Synthetic scenario fact
Top balance position	Raised	Turnover entry	Position does not establish the load path after pressure removal.	Historical source fact
Pressure trend	No historian tag identified for isolated branch.	Relevant interval	Cannot reconstruct transient pressure from trend data.	Not available
Leak-down test	Not performed before post-event disturbance.	After event	No direct rate measurement exists.	Not completed

Interpretive boundary

The record supports that B hydraulics were intended to be at zero pressure. It does not establish how the raised balance and carrier assembly were mechanically supported, nor whether movement occurred during pressure decay.