

Superseded Drawing Note - Similar Stand Variant

A synthetic, superseded engineering note found in an uncontrolled folder. It is deliberately easy to misuse if revision and equipment applicability are ignored.

Document ID	Incident	Record type	Status
R3-CH-001	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Document-control metadata

Field	Recorded value	Status
Title	Roughing Mill Carrier Link Retention - Stand Variant	Synthetic scenario fact
Revision	Rev D - superseded	Warning
Applies to	R2 legacy configuration; R3 applicability not established	Not established
Controlled-copy status	Uncontrolled scan; no current approval stamp	Low authority

Excerpt

The legacy note depicts a cap plate above the yoke pocket and calls it a positive link hold-down. A handwritten margin annotation says, 'same all roughers,' but the author and date of the annotation are not identified.

Required handling

- Do not apply the cap-plate requirement to R3 without a current R3 drawing or engineering confirmation.
- Treat the handwritten annotation as an unattributed claim.
- Retain the record because it may identify a design-history question, not because it proves an R3 defect.