

Shift Turnover Log - Turn 1 to Turn 2

A synthetic contemporaneous log used to test sequence, handoff, and unresolved-condition analysis.

Document ID	Incident	Record type	Status
R3-EV-006	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Turn 1 outgoing entry

Time	Entry	Author role
10/13 10:20 PM	R3 work rolls removed; roll-change equipment clear.	Maintenance shift lead
10/13 11:45 PM	Top and bottom backup rolls removed for outage scope.	Maintenance shift lead
10/14 12:25 AM	Top backup roll balance remains up. B hydraulic system isolated and bled for B-system work.	Energy-isolation lead
10/14 12:40 AM	Carrier-beam support / yoke seating not independently checked after roll removal.	Maintenance shift lead
10/14 12:55 AM	Turnover note: keep personnel clear below upper balance components until day-turn confirms final supported condition.	Maintenance shift lead

Turn 2 incoming entry

Field	Recorded value	Status
Outstanding condition acknowledged	General red-zone restriction acknowledged in verbal handoff.	Synthetic scenario fact
Specific carrier-beam / yoke verification	No entry found.	Gap in record
Formal re-brief before pit work	Morning contractor brief references overhead hazards but not the carrier-beam condition by name.	Synthetic scenario fact