

JJHAC / JSHA - R3 Mill Pit Outage Work

A synthetic pre-job hazard record modeled on the partner document family. It supports hazard-recognition and control-adequacy questions.

Document ID	Incident	Record type	Status
R3-EV-008	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Task and crew

Job / task	Applicable roles	Area	Brief time
R3 pit access and mill-stand outage support	Contractor mechanical crew; site maintenance liaison	R3 roughing mill / mill pit	10/14/2024 - 6:35 AM

Job steps, hazards, and controls

Step	Potential hazard	Recorded control	Assessment
Enter and work from pit / scaffold	Access, fall exposure, dropped objects from above.	Inspect scaffold; barricade work zone; hard hats; keep clear of overhead work.	Addressed generally
Work below mill stand	Suspended or unsecured mill components.	Verify no active crane lift; confirm equipment is under energy control.	Addressed generally
Hydraulic-system outage work	Stored pressure or unexpected motion.	Use ECP/LOTO; verify gauge zero; perform try.	Addressed
Changed roll configuration	Change in support path after roll removal.	No component-specific prompt for carrier beam / link / yoke seating.	Gap in specificity
Conditions change	New task, equipment state, or personnel.	Stop and revise brief before proceeding.	Defined

PPE and tools

Recorded: hard hat, safety glasses with side shields, safety footwear, gloves selected for task, hearing protection, fall protection where required by access condition. PPE does not replace control of falling-object or gravity-energy hazards.