

Preliminary Incident Notification - Record 16515

A test-ready transcription of the historical preliminary record supplied to the application with the initial incident description.

Document ID	Incident	Record type	Status
R3-START-001	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Facility	Area	Location	Event date / shift
Indiana Harbor	Hot Rolling and Finishing - 80-inch Hot Strip	Roughing Mill R3	10/14/2024 - Turn 2 - approximately 1:03 PM
Classification	Work type	Category	Potential severity
Preliminary contractor case / SIFp	Non-routine maintenance	Falling object	Death

Incident description

At approximately 1:03 PM on October 14, 2024, the R3 exit carrier beam fell from the yoke into the R3 mill pit, landing on the sled and a scaffold platform. No team members were in the pit at the time. Several contractor employees had worked in the pit during the morning, and two contractor employees walking beside the mill stand witnessed the fall.

The area was red-flagged for investigation. The carrier beam and its link were found intact with the keeper still installed. No damage was apparent on the yoke where the link rests. A small mill window liner from the top operator side fell with the beam. No crane lifts involving this equipment were in progress or had occurred prior.

On the previous shift, the work rolls and the top and bottom backup rolls had been removed in preparation for outage work in the mill stand. The R3 top backup roll balance had been left isolated in the raised position. The B hydraulics had been shut off and bled for work on that system.

Immediate actions

Stopped work and red-flagged the area; inspected other mill stands; ensured top roll balances were lowered; verified link-arm keepers were present at other stands; and held a safety stand-down.

Evidence identified in the preliminary record

Requested evidence	Availability at starter stage
Mechanical drawings	Not attached - request from document control / engineering.
Energy Control Plan (ECP)	Not attached - request incident-specific revision and execution record.
Lockout verification	Not attached - request signed field record.
Video	Not attached - request preserved clip and review log.
Pictures and measurements	Not attached - request original files and measurement sheet.

Preliminary cause field

Field	Recorded value	Status
Cause category	Work Environment - Other	Historical source fact
Investigation state	Still investigating	Open