

OEM / Engineering Information Request

An intentionally unresolved evidence request. It tests whether the investigation can keep a causal branch open while awaiting authoritative design information.

Document ID	Incident	Record type	Status
R3-EV-018	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Questions sent for authoritative response

Request	Why needed	Current status
Full carrier-beam, link, keeper, and yoke assembly drawing with revision history	Establish design intent, geometry, and positive-retention features.	Pending
Permitted balance positions during roll removal and hydraulic bleed-down	Determine whether the observed raised/isolation state was within approved configuration.	Pending
Required temporary blocking or restraint	Compare field record with manufacturer-defined gravity control.	Pending
Inspection limits for yoke and link contact surfaces	Evaluate wear and partial-seating hypotheses.	Pending
Known service bulletins or comparable events	Assess whether a latent design or known-condition pattern exists.	Pending

Investigation handling

Do not convert these requests into facts. Causes that depend on an OEM answer should remain provisional, with the missing evidence explicitly attached to the branch. Other supported branches may continue in parallel.