
Model
Input signal
RMS
RMS >
Threshold?
No
1
Gain
Yes
f(RMS)
Gain