

CDM Compliance Audit Report

Example Report — For Illustration Purposes Only

PROJECT DETAILS			
Project Title	Example Road Improvement Scheme — Phase 2	Project No.	EX-2026-CDM-001
Principal Designer	Acme Designs Ltd	Principal Contractor	Acus Construction Ltd
Client Rep / PM	J. Smith — Digital Revenue Studio	Report Month	March 2026
Check Date	20 March 2026	Check Type	Construction Phase — Monthly



45	38	4	3	4
Total items	In place / Y	Issues / N	N/A	Actions open


Pre-start / Mobilisation

Requirement	Timing	Status	Comments / Evidence
F10 notification (including any update) in place	Pre-start	Y	F10 submitted 14 Feb 2026, HSE ref EX-2026-0142
Key project personnel identified — Client Rep / PM	Pre-start	Y	J. Smith confirmed as Client PM
Principal Designer appointed	Pre-start	Y	Acme Designs Ltd appointed Jan 2026
Designer (Civil) appointed	Pre-start	Y	
Designer (Electrical) appointed	Pre-start	N/A	No electrical design element on this package
Principal Contractor appointed	Pre-start	Y	Acus Construction Ltd appointed Feb 2026
Contract Partners identified and competent	Pre-start	Y	CVs reviewed — all satisfactory
Pre-Construction SHE Information issued	4 Weeks Before	Y	Issued 28 Jan 2026
Construction Phase SHE Plan received and accepted	Pre-start	Y	Accepted 12 Feb 2026
RACI confirmed with Work Programme / Phases	4 Weeks Before	Y	
Principal Contractor's Organisation Chart in place	Pre-start	Y	Rev 3 issued 10 Mar 2026
Site Induction Presentation prepared	2 Weeks Before	Y	
Start / Finish dates for Construction Phase identified	Pre-start	Y	Start 3 Mar 2026 — Est. completion Dec 2027
Client Construction Phase Site Visit Meetings developed	Pre-start	Y	Monthly visits scheduled — next 15 Apr 2026
Project Progress Meetings scheduled / in diaries	Pre-start	Y	Bi-weekly — Wednesdays 09:00

Requirement	Timing	Status	Comments / Evidence
Site Mobilisation Visit completed	Pre-start	Y	Completed 28 Feb 2026
Pre-Start Meeting completed	Pre-start	Y	Completed 1 Mar 2026 — minutes on file

Construction Phase

Requirement	Timing	Status	Comments / Evidence
Safe access off the public highway	To Check	Y	Dedicated site access in place 
Access road around site suitable	To Check	Y	
Secure and fenced site compound	To Check	Y	Hoarding and fencing complete 
Access control barrier and site gatehouse	To Check	Y	Gatehouse staffed 07:00-18:00
Risk / hazard boards and SHE rules in place	To Check	Y	
Vehicle / pedestrian separation in place	To Check	N	Segregation compromised at compound entrance — ACTION raised  
Site office and staff welfare	To Check	Y	Welfare facilities confirmed adequate 
Plant quarantine area	To Check	Y	
Emergency response plan	To Check	Y	ERP posted in site office and welfare
Traffic management plan	To Check	Y	TMP Rev 4 approved 
ESQCR Compliance	To Check	N/A	No ESQCR items on this package
Temporary works design package identified	4 weeks prior	Y	TWD 001-005 approved
Site Supervision — suitable and sufficient	To Check	Y	Site Agent + 2 supervisors on site
Site Induction carried out — suitable and recorded	To Check	Y	47 workers inducted as of 20 Mar 2026
RAMS identified / agreed	To Check	Y	14 RAMS approved — 2 under review

Requirement	Timing	Status	Comments / Evidence
Site SHE Folder up-to-date	To Check	N	F10 notice not displayed — ACTION raised
Site Operative Register: Competency records and inducted	To Check	Y	
SHE Risk Register updated	To Check	Y	Updated 15 Mar 2026
Management of Construction Phase Plan effective	To Check	Y	CPP Rev 2 in use and distributed
Relevant parts of CPP provided to sub-contractors	To Check	Y	
Emergency Arrangements understood by workers	To Check	N	Muster point signage missing at northern compound — ACTION raised 
Incident reporting and investigation effective	To Check	Y	1 near miss reported and investigated this month
Client Construction Phase Site Visits completed	To Check	Y	Visit completed 20 Mar 2026
Assessment of work on / adjacent to live conductors	To Check	N/A	No live conductor works this phase
Management of Temporary Works effective	To Check	N	TWI not yet appointed — ACTION raised
Collection / collation of SHE File information	To Check	Y	SHE file folder maintained on shared drive

Running Action Log

No	Action Required	Owner	Entered	Due	Completed
1	Install physical segregation barrier at compound entrance to separate vehicle and pedestrian routes.	T. Walsh — Acus Construction	20/03/26	27/03/26	—
2	Display F10 notification in prominent location within site office and welfare facility.	T. Walsh — Acus Construction	20/03/26	22/03/26	—
3	Install muster point signage at northern compound. Confirm location with all workers at next toolbox talk.	K. Patel — Acus H&S; Advisor	20/03/26	24/03/26	—
4	Appoint Temporary Works Inspector (TWI) and confirm appointment in writing to Principal Designer.	Acus Contracts Manager	20/03/26	03/04/26	—

Photo Evidence Log — 6 photos across 5 items



Safe access off the public highway		In Place
Dedicated site access in place		
		
Photo 1		
Vehicle / pedestrian separation in place		Issue
Segregation compromised at compound entrance — ACTION raised		
		
Photo 1	Photo 2	
Site office and staff welfare		In Place
Welfare facilities confirmed adequate		
		
Photo 1		
Traffic management plan		In Place
TMP Rev 4 approved		

		
Photo 1		

Emergency Arrangements understood by workers		Issue
Muster point signage missing at northern compound — ACTION raised		
		
Photo 1		

Note: This is a fictitious example report created for illustration purposes only. All project names, company names, personnel names and reference numbers are entirely made up. Any resemblance to real projects, companies or individuals is coincidental. Placeholder images are used to illustrate the photo evidence feature — real reports show actual site photographs. © 2026 Digital Revenue Studio — digitalrevenuestudio.co.uk