2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Cramp School

Governance DISTRICT Report Type Elementary Address 3449 N. Mascher St. Enrollment 523 Grade Range '00-05' Philadelphia, Pa 19140 215-291-4704 / 215-291-5694 Phone/Fax **Admissions Category** Neighborhood

Website Www.Philasd.Org/Schools/Cramp Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)	Replacen	Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	65.28%	\$27,132,992	\$41,565,686
Building	64.60 %	\$25,678,231	\$39,750,240
Grounds	95.26 %	\$1,454,761	\$1,527,130

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.43 %	\$1,306,829	\$1,461,208
Exterior Walls (Shows condition of the structural condition of the exterior facade)	06.84 %	\$202,171	\$2,956,048
Windows (Shows functionality of exterior windows)	79.06 %	\$1,140,387	\$1,442,385
Exterior Doors (Shows condition of exterior doors)	329.38 %	\$382,507	\$116,128
Interior Doors (Classroom doors)	216.77 %	\$609,358	\$281,109
Interior Walls (Paint and Finishes)	140.86 %	\$1,490,253	\$1,057,962
Plumbing Fixtures	10.09 %	\$109,213	\$1,082,790
Boilers	151.03 %	\$2,258,226	\$1,495,243
Chillers/Cooling Towers	61.93 %	\$1,214,158	\$1,960,554
Radiators/Unit Ventilators/HVAC	190.73 %	\$6,566,754	\$3,442,983
Heating/Cooling Controls	158.90 %	\$1,718,053	\$1,081,188
Electrical Service and Distribution	301.74 %	\$2,344,063	\$776,854
Lighting	51.89 %	\$1,441,184	\$2,777,452
Communications and Security (Cameras, Pa System and Fire Alarm)	46.05 %	\$479,102	\$1,040,343

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.