2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

McClure School

Governance DISTRICT Report Type Elementary
Address 600 W. Hunting Park Ave. Enrollment 639
Philadelphia, Pa 19140 Grade Range '00-05'
Phone (Fax. 215-456-3001 / 215-456-5587 Admissions Category Neighborhoo

Phone/Fax 215-456-3001 / 215-456-5587 Admissions Category Neighborhood Website Www.Philasd.Org/Schools/Mcclure Turnaround Model N/A

Building/System FCI Tiers

| Facility Condition Index (FCI) = Cost of Assessed Deficiencies | | | | | | | |
|--|-------------------------------|---|--|--|--|--|--|
| raciiit | y Condition index (FCI) | Replacen | Replacement Value | | | | |
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% | | | |
| Buildings | | | | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. | | | |
| Systems | | | | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program | | | |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------|----------|--------------|------------------|
| Overall | 52.24% | \$17,431,937 | \$33,368,065 |
| Building | 50.75 % | \$16,705,231 | \$32,914,606 |
| Grounds | 104.53 % | \$697,604 | \$667,359 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|---|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 84.82 % | \$606,488 | \$715,004 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 00.00 % | \$0 | \$1,795,150 |
| Windows (Shows functionality of exterior windows) | 215.95 % | \$1,692,439 | \$783,725 |
| Exterior Doors (Shows condition of exterior doors) | 170.72 % | \$163,932 | \$96,025 |
| Interior Doors (Classroom doors) | 172.22 % | \$372,347 | \$216,200 |
| Interior Walls (Paint and Finishes) | 80.59 % | \$778,996 | \$966,575 |
| Plumbing Fixtures | 00.00 % | \$0 | \$1,815,850 |
| Boilers | 00.00 % | \$0 | \$1,073,525 |
| Chillers/Cooling Towers | 65.31 % | \$919,357 | \$1,407,600 |
| Radiators/Unit Ventilators/HVAC | 152.01 % | \$3,757,521 | \$2,471,925 |
| Heating/Cooling Controls | 158.90 % | \$1,233,498 | \$776,250 |
| Electrical Service and Distribution | 146.96 % | \$819,675 | \$557,750 |
| Lighting | 58.36 % | \$1,163,792 | \$1,994,100 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 99.68 % | \$744,554 | \$746,925 |

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.