#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## **Cassidy School**

Governance DISTRICT Report Type Elementarymiddle

Address 6523 Lansdowne Ave. Enrollment 470
Philadelphia, Pa 19151 Grade Range '00-07'

Phone/Fax 215-581-5506 / 215-581-5581 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Cassidy Turnaround Model N/A

# **Building/System FCI Tiers**

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies	
raciiit	y Condition index (FCI)	Replacem	nent Value	
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings		
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems	•	
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

### **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	80.57%	\$25,525,899	\$31,681,089
Building	82.54 %	\$24,971,234	\$30,252,903
Grounds	30.90 %	\$554,665	\$1,794,749

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	105.25 %	\$841,686	\$799,689
Exterior Walls (Shows condition of the structural condition of the exterior facade)	17.83 %	\$389,121	\$2,182,230
Windows (Shows functionality of exterior windows)	221.23 %	\$2,355,679	\$1,064,805
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$85,728
Interior Doors (Classroom doors)	142.36 %	\$295,426	\$207,522
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,163,541
Plumbing Fixtures	77.36 %	\$618,344	\$799,343
Boilers	130.34 %	\$1,438,673	\$1,103,826
Chillers/Cooling Towers	116.51 %	\$1,686,236	\$1,447,331
Radiators/Unit Ventilators/HVAC	296.92 %	\$7,546,932	\$2,541,698
Heating/Cooling Controls	161.26 %	\$1,287,125	\$798,161
Electrical Service and Distribution	114.08 %	\$654,229	\$573,493
Lighting	27.51 %	\$564,127	\$2,050,386
Communications and Security (Cameras, Pa System and Fire Alarm)	33.43 %	\$256,738	\$768,008

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.