### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## **Comly School**

GovernanceDISTRICTReport TypeElementaryAddress1001 Byberry Rd.Enrollment490Philadelphia, Pa 19116Grade Range'00-05'Phone/Fax215-961-2008 / 215-961-2555Admissions CategoryNeighborhood

Website Www.Philasd.Org/Schools/Comly Turnaround Model N/A

# **Building/System FCI Tiers**

Encilit	y Condition Index (FCI)	_ Cost of Assess	Cost of Assessed Deficiencies  Replacement Value			
raciiit	y Condition index (FCI)	Replacen				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	42.26%	\$18,281,699	\$43,255,417
Building	45.69 %	\$17,925,149	\$39,230,772
Grounds	09.20 %	\$356,549	\$3,875,559

#### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	90.94 %	\$1,288,473	\$1,416,868
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.45 %	\$9,779	\$2,191,644
Windows (Shows functionality of exterior windows)	186.93 %	\$1,788,572	\$956,826
Exterior Doors (Shows condition of exterior doors)	59.98 %	\$70,322	\$117,234
Interior Doors (Classroom doors)	75.98 %	\$200,545	\$263,952
Interior Walls (Paint and Finishes)	02.21 %	\$17,134	\$774,990
Plumbing Fixtures	17.83 %	\$395,329	\$2,216,916
Boilers	00.00 %	\$0	\$1,310,634
Chillers/Cooling Towers	70.09 %	\$1,204,455	\$1,718,496
Radiators/Unit Ventilators/HVAC	218.93 %	\$6,607,040	\$3,017,898
Heating/Cooling Controls	169.77 %	\$1,608,907	\$947,700
Electrical Service and Distribution	119.58 %	\$814,257	\$680,940
Lighting	15.74 %	\$383,105	\$2,434,536
Communications and Security (Cameras, Pa System and Fire Alarm)	66.12 %	\$602,970	\$911,898

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.