### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Huey School**

Governance CHARTER Report Type Elementarymiddle

 Address
 5200 Pine St.
 Enrollment
 567

 Philadelphia, Pa 19143
 Grade Range
 '00-08'

Phone/Fax N/A / N/A Admissions Category Neighborhood
Website Http://www.Glacharter.Org Turnaround Model Renaissance Charter

# **Building/System FCI Tiers**

Facilit	v Candition Inday (FCI)	_ Cost of Assess	ed Deficiencies	
raciiit	y Condition Index (FCI)	Replacen	Replacement Value	
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings		
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	55.77%	\$25,400,044	\$45,546,080
Building	56.84 %	\$24,868,445	\$43,749,458
Grounds	29.59 %	\$531,599	\$1,796,622

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.96 %	\$1,023,819	\$1,138,091
Exterior Walls (Shows condition of the structural condition of the exterior facade)	29.76 %	\$968,684	\$3,254,835
Windows (Shows functionality of exterior windows)	127.13 %	\$2,019,108	\$1,588,176
Exterior Doors (Shows condition of exterior doors)	75.98 %	\$97,153	\$127,865
Interior Doors (Classroom doors)	181.11 %	\$560,568	\$309,522
Interior Walls (Paint and Finishes)	89.07 %	\$1,320,352	\$1,482,356
Plumbing Fixtures	78.87 %	\$940,256	\$1,192,234
Boilers	00.00 %	\$0	\$1,646,377
Chillers/Cooling Towers	62.67 %	\$1,352,791	\$2,158,720
Radiators/Unit Ventilators/HVAC	125.48 %	\$4,756,784	\$3,790,987
Heating/Cooling Controls	158.90 %	\$1,891,710	\$1,190,471
Electrical Service and Distribution	79.25 %	\$677,919	\$855,375
Lighting	24.34 %	\$744,358	\$3,058,186
Communications and Security (Cameras, Pa System and Fire Alarm)	36.63 %	\$419,558	\$1,145,497

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.