## **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## **Girls High School**

Governance DISTRICT Report Type High Address 1400 W. Olney Ave. Enrollment 1005 Philadelphia, Pa 19141 Grade Range '09-12'

Phone/Fax 215-276-5258 / 215-276-5738 Admissions Category Special Admit

Website Www.Philasd.Org/Schools/Girlshigh Turnaround Model N/A

# **Building/System FCI Tiers**

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)	Replacem	Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	34.85%	\$47,275,639	\$135,645,947
Building	37.38 %	\$45,964,540	\$122,981,577
Grounds	10.35 %	\$1,311,099	\$12,664,370

#### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.65 %	\$20,346	\$3,134,294
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.86 %	\$87,058	\$10,081,670
Windows (Shows functionality of exterior windows)	02.87 %	\$184,208	\$6,422,397
Exterior Doors (Shows condition of exterior doors)	20.82 %	\$56,353	\$270,712
Interior Doors (Classroom doors)	204.47 %	\$1,794,188	\$877,479
Interior Walls (Paint and Finishes)	04.35 %	\$160,691	\$3,696,612
Plumbing Fixtures	28.59 %	\$901,994	\$3,155,189
Boilers	05.39 %	\$235,041	\$4,357,055
Chillers/Cooling Towers	66.52 %	\$3,800,523	\$5,712,947
Radiators/Unit Ventilators/HVAC	157.67 %	\$15,818,825	\$10,032,662
Heating/Cooling Controls	136.09 %	\$4,287,489	\$3,150,522
Electrical Service and Distribution	105.79 %	\$2,394,830	\$2,263,708
Lighting	40.81 %	\$3,303,081	\$8,093,341
Communications and Security (Cameras, Pa System and Fire Alarm)	52.51 %	\$1,591,716	\$3,031,502

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.