### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Hunter School**

Governance DISTRICT Report Type Elementarymiddle

Address 2400 N. Front St. Enrollment 530
Philadelphia, Pa 19133 Grade Range '00-08'

Phone/Fax 215-291-4710 / 215-291-5177 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Hunter Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	01.60%	\$825,146	\$51,535,234
Building	00.84 %	\$421,517	\$49,904,524
Grounds	24.75 %	\$403,629	\$1,630,710

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	03.83 %	\$67,764	\$1,768,144
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$3,635,635
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$1,773,985
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$142,825
Interior Doors (Classroom doors)	00.00 %	\$0	\$345,735
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,655,785
Plumbing Fixtures	00.00 %	\$0	\$1,331,720
Boilers	00.00 %	\$0	\$1,838,995
Chillers/Cooling Towers	00.00 %	\$0	\$2,411,280
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$4,234,515
Heating/Cooling Controls	00.00 %	\$0	\$1,329,750
Electrical Service and Distribution	00.00 %	\$0	\$955,450
Lighting	00.00 %	\$0	\$3,415,980
Communications and Security (Cameras, Pa System and Fire Alarm)	02.44 %	\$31,284	\$1,279,515

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.