## **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Spruance School**

Governance DISTRICT Report Type Elementarymiddle

Address 6401 Horrocks St. Enrollment 1521
Philadelphia, Pa 19149 Grade Range '00-08'

Phone/Fax 215-537-2514 / 215-537-2933 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Spruance Turnaround Model N/A

# **Building/System FCI Tiers**

Facilit	v Candition Inday (FCI)	_ Cost of Assess	<b>Cost of Assessed Deficiencies</b>		
raciiit	y Condition Index (FCI)	Replacen	Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%	
	Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.	
Systems					
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program	

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	42.62%	\$23,425,814	\$54,964,707
Building	45.14 %	\$23,171,369	\$51,335,274
Grounds	07.01 %	\$254,446	\$3,629,433

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	09.02 %	\$222,288	\$2,463,199
Exterior Walls (Shows condition of the structural condition of the exterior facade)	01.92 %	\$72,241	\$3,770,098
Windows (Shows functionality of exterior windows)	179.66 %	\$3,305,087	\$1,839,595
Exterior Doors (Shows condition of exterior doors)	08.87 %	\$13,140	\$148,107
Interior Doors (Classroom doors)	122.60 %	\$439,540	\$358,522
Interior Walls (Paint and Finishes)	07.86 %	\$106,093	\$1,349,309
Plumbing Fixtures	51.54 %	\$711,760	\$1,380,973
Boilers	59.79 %	\$1,140,278	\$1,907,010
Chillers/Cooling Towers	65.60 %	\$1,640,351	\$2,500,461
Radiators/Unit Ventilators/HVAC	186.10 %	\$8,172,082	\$4,391,128
Heating/Cooling Controls	158.90 %	\$2,191,180	\$1,378,931
Electrical Service and Distribution	37.60 %	\$372,503	\$990,787
Lighting	03.58 %	\$126,727	\$3,542,319
Communications and Security (Cameras, Pa System and Fire Alarm)	54.14 %	\$718,374	\$1,326,838

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

## **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Spruance LSH School**

Governance DISTRICT Report Type Elementarymiddle

Address 6401 Horrocks St. Enrollment

Philadelphia, Pa 19149 Grade Range '00-08'
Phone/Fax 215-537-2514 / 215-537-2933 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Spruance Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	v Candition Inday (ECI)		ed Deficiencies		
Facility Condition Index (FCI) =			Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%	
Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.	
		Systems			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program	

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	01.90%	\$349,287	\$18,377,729
Building	00.64 %	\$94,842	\$14,748,296
Grounds	07.01 %	\$254,446	\$3,629,433

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,030,080
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.62 %	\$4,843	\$781,000
Windows (Shows functionality of exterior windows)	00.23 %	\$768	\$340,968
Exterior Doors (Shows condition of exterior doors)	08.58 %	\$3,584	\$41,777
Interior Doors (Classroom doors)	11.89 %	\$11,188	\$94,060
Interior Walls (Paint and Finishes)	02.30 %	\$7,604	\$330,461
Plumbing Fixtures	00.00 %	\$0	\$790,005
Boilers	00.00 %	\$0	\$467,049
Chillers/Cooling Towers	00.00 %	\$0	\$612,392
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$1,075,438
Heating/Cooling Controls	00.00 %	\$0	\$337,716
Electrical Service and Distribution	00.00 %	\$0	\$242,655
Lighting	03.18 %	\$27,551	\$867,555
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$324,958

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.