2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Pennell School

Governance DISTRICT Report Type Elementary
Address 1800 Nedro Ave. Enrollment 410
Philadelphia, Pa 19141 Grade Range '00-05'

Phone/Fax 215-276-5267 / 215-549-4562 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Pennell Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	61.40%	\$21,901,496	\$35,672,317
Building	58.92 %	\$20,247,599	\$34,366,582
Grounds	126.66 %	\$1,653,897	\$1,305,735

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.59 %	\$508,230	\$567,300
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,602,081
Windows (Shows functionality of exterior windows)	132.07 %	\$1,676,853	\$1,269,669
Exterior Doors (Shows condition of exterior doors)	158.40 %	\$161,922	\$102,222
Interior Doors (Classroom doors)	424.14 %	\$1,049,529	\$247,448
Interior Walls (Paint and Finishes)	82.06 %	\$677,388	\$825,479
Plumbing Fixtures	04.77 %	\$45,475	\$953,133
Boilers	84.61 %	\$1,113,599	\$1,316,198
Chillers/Cooling Towers	65.60 %	\$1,132,165	\$1,725,791
Radiators/Unit Ventilators/HVAC	138.15 %	\$4,187,043	\$3,030,709
Heating/Cooling Controls	158.90 %	\$1,512,330	\$951,723
Electrical Service and Distribution	159.95 %	\$1,093,818	\$683,831
Lighting	51.89 %	\$1,268,679	\$2,444,871
Communications and Security (Cameras, Pa System and Fire Alarm)	49.55 %	\$453,783	\$915,769

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.