#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

# Washington, Martha School

Governance DISTRICT Report Type Elementarymiddle

 Address
 766 N. 44Th St.
 Enrollment
 408

 Philadelphia, Pa 19104
 Grade Range
 '00-08'

Phone/Fax 215-823-8203 / 215-823-8292 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Marthawashington Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies						
raciiit	y Condition index (FCI)	Replacem	Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	54.57%	\$20,453,154	\$37,480,831
Building	56.54 %	\$20,027,113	\$35,421,473
Grounds	18.38 %	\$426,041	\$2,317,464

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.25 %	\$711,522	\$797,238
Exterior Walls (Shows condition of the structural condition of the exterior facade)	26.02 %	\$684,870	\$2,631,683
Windows (Shows functionality of exterior windows)	139.45 %	\$1,790,757	\$1,284,113
Exterior Doors (Shows condition of exterior doors)	46.99 %	\$48,576	\$103,385
Interior Doors (Classroom doors)	104.15 %	\$260,643	\$250,263
Interior Walls (Paint and Finishes)	80.55 %	\$965,955	\$1,199,266
Plumbing Fixtures	42.66 %	\$411,250	\$963,976
Boilers	02.46 %	\$32,716	\$1,331,171
Chillers/Cooling Towers	41.40 %	\$722,673	\$1,745,424
Radiators/Unit Ventilators/HVAC	78.26 %	\$2,398,693	\$3,065,187
Heating/Cooling Controls	158.48 %	\$1,525,418	\$962,550
Electrical Service and Distribution	100.61 %	\$695,798	\$691,610
Lighting	23.80 %	\$588,433	\$2,472,684
Communications and Security (Cameras, Pa System and Fire Alarm)	18.52 %	\$171,486	\$926,187

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.