2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Powel School

GovernanceDISTRICTReport TypeElementaryAddress301 N. 36Th St.Enrollment282Philadelphia, Pa 19104Grade Range'00-04'Phone/Fax215-823-8201 / 215-823-8215Admissions CategoryNeighborhood

Website Www.Philasd.Org/Schools/Powel Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	47.09%	\$5,335,102	\$11,328,546
Building	48.35 %	\$4,979,149	\$10,297,412
Grounds	33.95 %	\$355,954	\$1,048,594

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	87.83 %	\$336,841	\$383,534
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.59 %	\$3,329	\$561,960
Windows (Shows functionality of exterior windows)	279.37 %	\$685,416	\$245,340
Exterior Doors (Shows condition of exterior doors)	215.46 %	\$64,769	\$30,060
Interior Doors (Classroom doors)	41.12 %	\$27,828	\$67,680
Interior Walls (Paint and Finishes)	68.88 %	\$243,860	\$354,060
Plumbing Fixtures	05.52 %	\$31,386	\$568,440
Boilers	00.00 %	\$0	\$336,060
Chillers/Cooling Towers	43.73 %	\$192,713	\$440,640
Radiators/Unit Ventilators/HVAC	83.80 %	\$648,423	\$773,820
Heating/Cooling Controls	158.90 %	\$386,138	\$243,000
Electrical Service and Distribution	172.13 %	\$300,543	\$174,600
Lighting	31.21 %	\$194,830	\$624,240
Communications and Security (Cameras, Pa System and Fire Alarm)	175.04 %	\$409,287	\$233,820

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.