2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Harrity School

Governance CHARTER Report Type Elementarymiddle

Address 5601 Christian St. Enrollment 849
Philadelphia, Pa 19143 Grade Range '00-08'

 Phone/Fax
 215-471-2908 / N/A
 Admissions Category
 Neighborhood

 Website
 Www.Masterycharter.Org/Schools/Harrity Turnaround Model
 Renaissance Charter

Campus/

Building/System FCI Tiers

Cost of Assessed Deficiencies							
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	38.00%	\$14,304,632	\$37,640,973
Building	38.42 %	\$13,977,388	\$36,382,306
Grounds	25.97 %	\$327,244	\$1,260,105

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	02.99 %	\$20,346	\$680,760
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,654,087
Windows (Shows functionality of exterior windows)	106.16 %	\$1,374,852	\$1,295,045
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$104,265
Interior Doors (Classroom doors)	378.03 %	\$954,117	\$252,394
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,139,006
Plumbing Fixtures	04.71 %	\$45,810	\$972,183
Boilers	00.00 %	\$0	\$1,342,504
Chillers/Cooling Towers	65.60 %	\$1,154,800	\$1,760,283
Radiators/Unit Ventilators/HVAC	128.47 %	\$3,971,512	\$3,091,282
Heating/Cooling Controls	158.90 %	\$1,542,557	\$970,745
Electrical Service and Distribution	143.93 %	\$1,003,883	\$697,498
Lighting	08.00 %	\$199,459	\$2,493,735
Communications and Security (Cameras, Pa System and Fire Alarm)	10.15 %	\$94,824	\$934,072

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.