#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Hopkinson School**

Governance DISTRICT Report Type Elementarymiddle

 Address
 4001 L St.
 Enrollment
 922

 Philadelphia, Pa 19124
 Grade Range
 '00-08'

Phone/Fax 215-537-2526 / 215-537-2900 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Hopkinson Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	v Condition Index (ECI)		ed Deficiencies			
Facility Condition Index (FCI) = Replacement Value						
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
	Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

#### **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	50.56%	\$17,006,739	\$33,634,550
Building	51.84 %	\$16,795,172	\$32,399,990
Grounds	17.14 %	\$211,567	\$1,234,560

#### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	39.55 %	\$307,456	\$777,343
Exterior Walls (Shows condition of the structural condition of the exterior facade)	06.61 %	\$158,640	\$2,399,150
Windows (Shows functionality of exterior windows)	166.03 %	\$1,943,654	\$1,170,650
Exterior Doors (Shows condition of exterior doors)	137.44 %	\$129,537	\$94,250
Interior Doors (Classroom doors)	239.80 %	\$547,100	\$228,150
Interior Walls (Paint and Finishes)	30.60 %	\$334,333	\$1,092,650
Plumbing Fixtures	79.11 %	\$695,213	\$878,800
Boilers	108.10 %	\$1,311,841	\$1,213,550
Chillers/Cooling Towers	52.26 %	\$831,584	\$1,591,200
Radiators/Unit Ventilators/HVAC	139.03 %	\$3,884,975	\$2,794,350
Heating/Cooling Controls	102.06 %	\$895,570	\$877,500
Electrical Service and Distribution	134.46 %	\$847,757	\$630,500
Lighting	40.68 %	\$916,957	\$2,254,200
Communications and Security (Cameras, Pa System and Fire Alarm)	84.83 %	\$716,265	\$844,350

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Hopkinson LSH School**

Governance DISTRICT Report Type Elementarymiddle

Address 4001 L St. Enrollment

Philadelphia, Pa 19124 Grade Range '00-08'
Phone/Fax 215-537-2526 / 215-537-2900 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Hopkinson Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
	Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

#### **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	07.13%	\$767,242	\$10,754,458
Building	05.84 %	\$555,675	\$9,519,898
Grounds	17.14 %	\$211,567	\$1,234,560

#### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	00.00 %	\$0	\$637,071
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$499,770
Windows (Shows functionality of exterior windows)	02.25 %	\$4,912	\$218,189
Exterior Doors (Shows condition of exterior doors)	60.88 %	\$16,274	\$26,733
Interior Doors (Classroom doors)	28.11 %	\$16,922	\$60,190
Interior Walls (Paint and Finishes)	08.88 %	\$22,506	\$253,567
Plumbing Fixtures	00.00 %	\$0	\$505,533
Boilers	00.00 %	\$0	\$298,869
Chillers/Cooling Towers	00.00 %	\$0	\$391,876
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$688,184
Heating/Cooling Controls	158.82 %	\$343,231	\$216,108
Electrical Service and Distribution	00.00 %	\$0	\$155,278
Lighting	00.32 %	\$1,765	\$555,157
Communications and Security (Cameras, Pa System and Fire Alarm)	70.43 %	\$146,460	\$207,944

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.