#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Potter-Thomas School**

Governance DISTRICT Report Type Elementarymiddle

Address 3001 N. 6Th St. Enrollment 582
Philadelphia, Pa 19133 Grade Range '00-08'

Phone/Fax 215-227-4423 / 215-227-7196 Admissions Category Neighborhood Website Www.Philasd.Org/Schools/Potterthomas Turnaround Model Turnaround

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)	Replacen	Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

# **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	38.65%	\$16,140,793	\$41,763,023
Building	36.59 %	\$14,714,696	\$40,215,252
Grounds	68.22 %	\$1,426,095	\$2,090,557

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.66 %	\$1,680,221	\$1,873,916
Exterior Walls (Shows condition of the structural condition of the exterior facade)	06.57 %	\$193,737	\$2,950,327
Windows (Shows functionality of exterior windows)	64.01 %	\$921,461	\$1,439,593
Exterior Doors (Shows condition of exterior doors)	235.73 %	\$273,220	\$115,903
Interior Doors (Classroom doors)	124.98 %	\$350,638	\$280,565
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,055,915
Plumbing Fixtures	05.61 %	\$60,634	\$1,080,694
Boilers	56.45 %	\$842,405	\$1,492,349
Chillers/Cooling Towers	00.00 %	\$0	\$1,956,760
Radiators/Unit Ventilators/HVAC	124.67 %	\$4,284,083	\$3,436,320
Heating/Cooling Controls	158.90 %	\$1,714,730	\$1,079,096
Electrical Service and Distribution	41.69 %	\$323,269	\$775,350
Lighting	18.11 %	\$502,124	\$2,772,076
Communications and Security (Cameras, Pa System and Fire Alarm)	24.68 %	\$256,233	\$1,038,330

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.