2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Engineering and Science (Carver) School

Middlehigh Governance DISTRICT Report Type Address 1600 W. Norris St. Enrollment 900 '07-12' Philadelphia, Pa 19121 Grade Range Phone/Fax

215-684-5079 / 215-684-5151 Admissions Category Special Admit

Website Www.Carver.Phila.K12.Pa.Us Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	02.01%	\$1,575,145	\$78,489,877
Building	02.00 %	\$1,525,991	\$76,257,165
Grounds	02.20 %	\$49,154	\$2,232,712

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	55.99 %	\$1,016,460	\$1,815,360
Exterior Walls (Shows condition of the structural condition of the exterior facade)	02.60 %	\$168,382	\$6,471,792
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$4,122,771
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$173,780
Interior Doors (Classroom doors)	00.00 %	\$0	\$563,286
Interior Walls (Paint and Finishes)	02.33 %	\$33,869	\$1,452,000
Plumbing Fixtures	00.00 %	\$0	\$2,025,431
Boilers	00.00 %	\$0	\$2,796,953
Chillers/Cooling Towers	00.00 %	\$0	\$3,667,349
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$6,440,332
Heating/Cooling Controls	00.00 %	\$0	\$2,022,435
Electrical Service and Distribution	02.91 %	\$42,237	\$1,453,157
Lighting	00.43 %	\$22,343	\$5,195,411
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$1,946,032

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.