#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## **Bryant School**

Governance DISTRICT Report Type Elementarymiddle

Address6001 Cedar Ave.<br/>Philadelphia, Pa 19143Enrollment400Phone/Fax215-471-2910 / 215-471-8379Admissions CategoryNeighborhoodWebsiteWww.Philasd.Org/Schools/BryantTurnaround ModelTurnaround

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	Cost of Assess	ed Deficiencies			
raciiit	y condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
	•	Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

### **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	39.77%	\$19,187,219	\$48,248,991
Building	39.73 %	\$18,796,497	\$47,304,730
Grounds	22.84 %	\$390,722	\$1,710,391

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	43.82 %	\$515,848	\$1,177,237
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$3,478,214
Windows (Shows functionality of exterior windows)	53.52 %	\$908,306	\$1,697,172
Exterior Doors (Shows condition of exterior doors)	10.23 %	\$13,975	\$136,641
Interior Doors (Classroom doors)	90.06 %	\$297,878	\$330,765
Interior Walls (Paint and Finishes)	14.42 %	\$143,070	\$992,295
Plumbing Fixtures	12.86 %	\$163,835	\$1,274,057
Boilers	00.00 %	\$0	\$1,759,367
Chillers/Cooling Towers	40.73 %	\$939,475	\$2,306,873
Radiators/Unit Ventilators/HVAC	54.85 %	\$2,222,243	\$4,051,163
Heating/Cooling Controls	158.51 %	\$2,016,494	\$1,272,173
Electrical Service and Distribution	87.28 %	\$797,786	\$914,080
Lighting	07.19 %	\$235,117	\$3,268,070
Communications and Security (Cameras, Pa System and Fire Alarm)	32.51 %	\$397,964	\$1,224,113

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.