2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Vare at Washington Elementary School

Governance DISTRICT Report Type Elementarymiddle

 Address
 1198 S. 5Th St.
 Enrollment
 366

 Philadelphia, Pa 19147
 Grade Range
 '00-08'

Phone/Fax 215-952-8620 / 215-952-8508 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Avare Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	36.13%	\$12,783,619	\$35,377,982
Building	34.92 %	\$12,238,759	\$35,051,109
Grounds	90.26 %	\$544,860	\$603,633

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$873,806
Exterior Walls (Shows condition of the structural condition of the exterior facade)	01.29 %	\$32,460	\$2,509,880
Windows (Shows functionality of exterior windows)	88.59 %	\$1,084,921	\$1,224,680
Exterior Doors (Shows condition of exterior doors)	129.31 %	\$127,502	\$98,600
Interior Doors (Classroom doors)	14.92 %	\$35,620	\$238,680
Interior Walls (Paint and Finishes)	04.05 %	\$46,262	\$1,143,080
Plumbing Fixtures	07.00 %	\$64,361	\$919,360
Boilers	00.00 %	\$0	\$1,269,560
Chillers/Cooling Towers	49.20 %	\$819,029	\$1,664,640
Radiators/Unit Ventilators/HVAC	115.10 %	\$3,364,864	\$2,923,320
Heating/Cooling Controls	158.90 %	\$1,458,745	\$918,000
Electrical Service and Distribution	107.63 %	\$709,940	\$659,600
Lighting	29.70 %	\$700,282	\$2,358,240
Communications and Security (Cameras, Pa System and Fire Alarm)	47.72 %	\$421,527	\$883,320

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.