2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Birney School

Governance CHARTER Report Type Elementarymiddle

Address 900 Lindley Ave. Enrollment

Philadelphia, Pa 19141 '00-08' Grade Range

215-456-3000 / 215-457-6695 Phone/Fax Admissions Category Neighborhood Website Www.Birneyprep.Com/ Turnaround Model Renaissance Charter

Building/System FCI Tiers

Cost of Assessed Deficiencies							
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	43.30%	\$13,399,870	\$30,943,240
Building	50.58 %	\$13,024,478	\$25,751,772
Grounds	28.78 %	\$375,392	\$1,304,276

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	92.40 %	\$447,879	\$484,700
Exterior Walls (Shows condition of the structural condition of the exterior facade)	09.84 %	\$187,453	\$1,905,056
Windows (Shows functionality of exterior windows)	166.14 %	\$1,545,191	\$930,032
Exterior Doors (Shows condition of exterior doors)	149.07 %	\$111,196	\$74,592
Interior Doors (Classroom doors)	480.85 %	\$853,997	\$177,600
Interior Walls (Paint and Finishes)	03.36 %	\$26,966	\$801,568
Plumbing Fixtures	01.87 %	\$13,267	\$708,624
Boilers	14.51 %	\$142,120	\$979,168
Chillers/Cooling Towers	66.45 %	\$853,284	\$1,284,048
Radiators/Unit Ventilators/HVAC	95.57 %	\$2,154,010	\$2,253,744
Heating/Cooling Controls	155.54 %	\$1,100,337	\$707,440
Electrical Service and Distribution	53.44 %	\$246,776	\$461,760
Lighting	61.75 %	\$1,020,602	\$1,652,864
Communications and Security (Cameras, Pa System and Fire Alarm)	65.13 %	\$403,314	\$619,232

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.