2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Webster School

Governance DISTRICT Report Type Elementary Address 3400 Frankford Ave. Enrollment 851 '00-05' Philadelphia, Pa 19134 **Grade Range** Phone/Fax 215-537-2525 / 215-537-2517 **Admissions Category**

Neighborhood Website Www.Philasd.Org/Schools/Webster Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	Cost of Assess	ed Deficiencies		
raciiit	y condition index (FCI)		Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%	
Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.	
	•	Systems			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program	

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	35.62%	\$18,459,344	\$51,820,170
Building	36.22 %	\$18,258,210	\$50,415,444
Grounds	14.32 %	\$201,134	\$1,404,726

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	88.14 %	\$1,456,926	\$1,652,920
Exterior Walls (Shows condition of the structural condition of the exterior facade)	07.44 %	\$214,232	\$2,880,826
Windows (Shows functionality of exterior windows)	43.00 %	\$540,833	\$1,257,708
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$154,099
Interior Doors (Classroom doors)	27.50 %	\$95,412	\$346,954
Interior Walls (Paint and Finishes)	18.54 %	\$270,955	\$1,461,636
Plumbing Fixtures	00.00 %	\$0	\$2,914,045
Boilers	00.00 %	\$0	\$1,722,774
Chillers/Cooling Towers	00.00 %	\$0	\$2,258,892
Radiators/Unit Ventilators/HVAC	140.33 %	\$5,566,583	\$3,966,902
Heating/Cooling Controls	146.67 %	\$1,827,090	\$1,245,713
Electrical Service and Distribution	295.44 %	\$2,644,413	\$895,068
Lighting	04.50 %	\$143,951	\$3,200,097
Communications and Security (Cameras, Pa System and Fire Alarm)	48.14 %	\$576,986	\$1,198,652

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Webster LSH School

Governance DISTRICT Report Type Elementary

Address 3400 Frankford Ave. Enrollment

Philadelphia, Pa 19134 Grade Range '00-05'
Phone/Fax 215-537-2525 / 215-537-2517 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Webster Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies		
raciiit	y Condition index (FCI)		Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%	
Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.	
		Systems	•		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program	

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	01.46%	\$212,376	\$14,507,941
Building	00.08 %	\$11,242	\$13,386,023
Grounds	14.32 %	\$201,134	\$1,404,726

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$984,828
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.85 %	\$6,458	\$761,144
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$332,299
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$40,715
Interior Doors (Classroom doors)	00.00 %	\$0	\$91,669
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$322,060
Plumbing Fixtures	00.00 %	\$0	\$769,920
Boilers	00.00 %	\$0	\$455,175
Chillers/Cooling Towers	00.00 %	\$0	\$596,822
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$1,048,096
Heating/Cooling Controls	00.00 %	\$0	\$329,130
Electrical Service and Distribution	00.00 %	\$0	\$236,486
Lighting	00.00 %	\$0	\$845,498
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$316,696

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.