### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## **Stearne School**

Governance DISTRICT Report Type Elementarymiddle

 Address
 1655 Unity St.
 Enrollment
 570

 Philadelphia, Pa 19124
 Grade Range
 '00-08'

Phone/Fax 215-537-2522 / 215-537-2918 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Stearne Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
		Systems					
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	41.43%	\$16,161,246	\$39,010,814
Building	42.07 %	\$15,973,555	\$37,972,253
Grounds	18.07 %	\$187,690	\$1,038,561

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.59 %	\$982,646	\$1,096,856
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.75 %	\$20,973	\$2,810,697
Windows (Shows functionality of exterior windows)	19.28 %	\$264,407	\$1,371,462
Exterior Doors (Shows condition of exterior doors)	63.28 %	\$69,873	\$110,418
Interior Doors (Classroom doors)	155.37 %	\$415,290	\$267,287
Interior Walls (Paint and Finishes)	02.24 %	\$22,506	\$1,005,942
Plumbing Fixtures	24.80 %	\$255,278	\$1,029,548
Boilers	35.47 %	\$504,334	\$1,421,721
Chillers/Cooling Towers	05.71 %	\$106,501	\$1,864,152
Radiators/Unit Ventilators/HVAC	179.69 %	\$5,882,507	\$3,273,689
Heating/Cooling Controls	156.50 %	\$1,608,907	\$1,028,025
Electrical Service and Distribution	108.99 %	\$805,046	\$738,655
Lighting	50.33 %	\$1,329,060	\$2,640,882
Communications and Security (Cameras, Pa System and Fire Alarm)	43.86 %	\$433,898	\$989,189

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.