# **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## Lea School

Governance DISTRICT Report Type Elementarymiddle

 Address
 4700 Locust St.
 Enrollment
 537

 Philadelphia, Pa 19139
 Grade Range
 '00-08'

Phone/Fax 215-471-2915 / 215-471-4355 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Lea Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

# **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	39.40%	\$14,336,138	\$36,383,366
Building	39.18 %	\$14,000,166	\$35,730,893
Grounds	31.12 %	\$335,972	\$1,079,473

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	08.72 %	\$108,674	\$1,246,604
Exterior Walls (Shows condition of the structural condition of the exterior facade)	24.99 %	\$645,789	\$2,583,700
Windows (Shows functionality of exterior windows)	163.68 %	\$2,063,472	\$1,260,700
Exterior Doors (Shows condition of exterior doors)	07.98 %	\$8,096	\$101,500
Interior Doors (Classroom doors)	271.83 %	\$667,882	\$245,700
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,176,700
Plumbing Fixtures	17.24 %	\$163,161	\$946,400
Boilers	00.00 %	\$0	\$1,306,900
Chillers/Cooling Towers	51.47 %	\$881,947	\$1,713,600
Radiators/Unit Ventilators/HVAC	62.29 %	\$1,874,387	\$3,009,300
Heating/Cooling Controls	158.90 %	\$1,501,644	\$945,000
Electrical Service and Distribution	79.95 %	\$542,863	\$679,000
Lighting	24.37 %	\$591,570	\$2,427,600
Communications and Security (Cameras, Pa System and Fire Alarm)	46.85 %	\$425,974	\$909,300

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.