### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Finletter School**

Governance DISTRICT Report Type Elementarymiddle

 Address
 6100 N. Front St.
 Enrollment
 749

 Philadelphia, Pa 19120
 Grade Range
 '00-08'

Phone/Fax 215-276-5265 / 215-276-5285 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Finletter Turnaround Model N/A

# **Building/System FCI Tiers**

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)	Replacem	Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
	Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	51.54%	\$17,470,075	\$33,898,021
Building	54.67 %	\$17,213,080	\$31,484,979
Grounds	10.01 %	\$256,996	\$2,566,176

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	23.70 %	\$187,586	\$791,412
Exterior Walls (Shows condition of the structural condition of the exterior facade)	09.93 %	\$230,062	\$2,316,472
Windows (Shows functionality of exterior windows)	159.49 %	\$1,802,775	\$1,130,308
Exterior Doors (Shows condition of exterior doors)	142.35 %	\$129,537	\$91,002
Interior Doors (Classroom doors)	171.14 %	\$377,002	\$220,288
Interior Walls (Paint and Finishes)	11.03 %	\$109,625	\$994,119
Plumbing Fixtures	07.87 %	\$66,795	\$848,515
Boilers	89.62 %	\$1,050,122	\$1,171,729
Chillers/Cooling Towers	162.38 %	\$2,494,726	\$1,536,365
Radiators/Unit Ventilators/HVAC	98.29 %	\$2,652,016	\$2,698,052
Heating/Cooling Controls	189.90 %	\$1,608,907	\$847,260
Electrical Service and Distribution	111.56 %	\$679,157	\$608,772
Lighting	52.76 %	\$1,148,324	\$2,176,517
Communications and Security (Cameras, Pa System and Fire Alarm)	68.82 %	\$561,084	\$815,252

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

# **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Finletter LSH School**

Governance DISTRICT Report Type Elementarymiddle

Address 6100 N. Front St. Enrollment

Philadelphia, Pa 19120 Grade Range '00-08'
Phone/Fax 215-276-5265 / 215-276-5285 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Finletter Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	v Condition Index (ECI)	_ Cost of Assess	ed Deficiencies			
Facility Condition Index (FCI) =			Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
	Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	20.61%	\$3,393,327	\$16,468,311
Building	06.26 %	\$870,951	\$13,902,135
Grounds	10.01 %	\$256,996	\$2,566,176

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	00.00 %	\$0	\$934,787
Exterior Walls (Shows condition of the structural condition of the exterior facade)	02.27 %	\$16,648	\$734,388
Windows (Shows functionality of exterior windows)	16.76 %	\$53,727	\$320,618
Exterior Doors (Shows condition of exterior doors)	10.64 %	\$4,181	\$39,283
Interior Doors (Classroom doors)	05.19 %	\$4,589	\$88,446
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$395,421
Plumbing Fixtures	00.00 %	\$0	\$742,856
Boilers	00.00 %	\$0	\$439,174
Chillers/Cooling Towers	08.54 %	\$49,157	\$575,843
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$1,011,254
Heating/Cooling Controls	132.68 %	\$421,330	\$317,561
Electrical Service and Distribution	00.00 %	\$0	\$228,173
Lighting	02.02 %	\$16,476	\$815,778
Communications and Security (Cameras, Pa System and Fire Alarm)	93.15 %	\$284,621	\$305,564

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.