#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Bodine School**

Governance DISTRICT Report Type High Address 1101 N. 4Th St. Enrollment 508 Philadelphia, Pa 19123 Grade Range '09-12'

Phone/Fax 215-351-7332 / 215-351-7370 Admissions Category Special Admit

Website Www.Philasd.Org/Schools/Bodine Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

# **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	64.87%	\$19,583,062	\$30,190,290
Building	59.43 %	\$18,426,080	\$31,003,193
Grounds	208.62 %	\$1,156,982	\$554,590

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	90.61 %	\$654,657	\$722,477
Exterior Walls (Shows condition of the structural condition of the exterior facade)	37.73 %	\$961,698	\$2,548,800
Windows (Shows functionality of exterior windows)	205.93 %	\$3,343,586	\$1,623,680
Exterior Doors (Shows condition of exterior doors)	239.53 %	\$163,932	\$68,440
Interior Doors (Classroom doors)	94.88 %	\$210,482	\$221,840
Interior Walls (Paint and Finishes)	34.15 %	\$338,694	\$991,790
Plumbing Fixtures	23.52 %	\$187,630	\$797,680
Boilers	87.75 %	\$966,605	\$1,101,530
Chillers/Cooling Towers	63.58 %	\$918,346	\$1,444,320
Radiators/Unit Ventilators/HVAC	154.62 %	\$3,921,898	\$2,536,410
Heating/Cooling Controls	158.90 %	\$1,265,676	\$796,500
Electrical Service and Distribution	41.04 %	\$234,864	\$572,300
Lighting	55.38 %	\$1,133,077	\$2,046,120
Communications and Security (Cameras, Pa System and Fire Alarm)	77.68 %	\$595,356	\$766,410

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.