2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Gideon School

Governance DISTRICT Report Type Elementarymiddle

Address 2817 W. Glenwood Ave. Enrollment 284
Philadelphia, Pa 19121 Grade Range '00-08'

Phone/Fax 215-684-5072 / 215-684-8917 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Gideon Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	42.77%	\$14,912,336	\$34,862,490
Building	44.06 %	\$14,728,531	\$33,426,720
Grounds	30.79 %	\$442,029	\$1,435,770

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$942,507
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.52 %	\$12,916	\$2,472,970
Windows (Shows functionality of exterior windows)	144.27 %	\$1,740,920	\$1,206,670
Exterior Doors (Shows condition of exterior doors)	90.53 %	\$87,948	\$97,150
Interior Doors (Classroom doors)	164.31 %	\$386,418	\$235,170
Interior Walls (Paint and Finishes)	49.37 %	\$650,959	\$1,318,560
Plumbing Fixtures	39.50 %	\$357,793	\$905,840
Boilers	00.00 %	\$0	\$1,250,890
Chillers/Cooling Towers	64.08 %	\$1,051,043	\$1,640,160
Radiators/Unit Ventilators/HVAC	130.46 %	\$3,757,540	\$2,880,330
Heating/Cooling Controls	158.90 %	\$1,437,288	\$904,500
Electrical Service and Distribution	109.27 %	\$710,160	\$649,900
Lighting	39.72 %	\$922,940	\$2,323,560
Communications and Security (Cameras, Pa System and Fire Alarm)	86.57 %	\$753,483	\$870,330

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.