#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Alcorn School**

Governance CHARTER Report Type Elementarymiddle

Address 3200 Dickinson St. Enrollment 607
Philadelphia, Pa 19146 Grade Range '00-08'

Phone/Fax 215-952-6219 / N/A Admissions Category Neighborhood Website Www.Universalcompanies.Org/Education/Alcorn- Turnaround Model Renaissance Chart

Www.Universalcompanies.Org/Education/Alcorn- Turnaround Model Renaissance Charter Charter-Elementary-School/

## **Building/System FCI Tiers**

Cost of Assessed Deficiencies							
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	50.34%	\$15,826,679	\$31,437,568
Building	47.66 %	\$15,063,688	\$31,606,235
Grounds	57.53 %	\$762,990	\$1,326,323

# **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	06.83 %	\$40,692	\$595,665
Exterior Walls (Shows condition of the structural condition of the exterior facade)	03.47 %	\$80,724	\$2,325,330
Windows (Shows functionality of exterior windows)	126.02 %	\$1,429,846	\$1,134,630
Exterior Doors (Shows condition of exterior doors)	139.58 %	\$127,502	\$91,350
Interior Doors (Classroom doors)	215.74 %	\$477,059	\$221,130
Interior Walls (Paint and Finishes)	01.92 %	\$20,322	\$1,057,770
Plumbing Fixtures	00.00 %	\$0	\$851,760
Boilers	00.00 %	\$0	\$1,176,210
Chillers/Cooling Towers	65.60 %	\$1,011,742	\$1,542,240
Radiators/Unit Ventilators/HVAC	145.98 %	\$3,953,687	\$2,708,370
Heating/Cooling Controls	158.90 %	\$1,351,482	\$850,500
Electrical Service and Distribution	129.66 %	\$792,358	\$611,100
Lighting	22.23 %	\$485,734	\$2,184,840
Communications and Security (Cameras, Pa System and Fire Alarm)	50.57 %	\$413,885	\$818,370

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.