2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Greenfield School

Governance DISTRICT Report Type Elementarymiddle

Address 2200 Chestnut St. Enrollment 623
Philadelphia, Pa 19103 Grade Range '00-08'

Phone/Fax 215-299-3566 / 215-299-3567 Admissions Category Neighborhood

Website Www.Centercityschools.Com/Greenfield/ Turnaround Model N/A

Building/System FCI Tiers

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies		
raciiit	y Condition index (FCI)	Replacem	Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%	
		Buildings			
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.	
		Systems	•		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program	

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	39.18%	\$18,738,245	\$47,825,662
Building	37.69 %	\$17,696,107	\$46,956,360
Grounds	119.09 %	\$1,042,137	\$875,062

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	97.62 %	\$993,492	\$1,017,728
Exterior Walls (Shows condition of the structural condition of the exterior facade)	22.20 %	\$786,572	\$3,543,360
Windows (Shows functionality of exterior windows)	113.71 %	\$1,966,009	\$1,728,960
Exterior Doors (Shows condition of exterior doors)	65.43 %	\$91,073	\$139,200
Interior Doors (Classroom doors)	141.58 %	\$477,059	\$336,960
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,268,160
Plumbing Fixtures	00.00 %	\$0	\$1,297,920
Boilers	12.72 %	\$227,915	\$1,792,320
Chillers/Cooling Towers	02.50 %	\$58,782	\$2,350,080
Radiators/Unit Ventilators/HVAC	92.66 %	\$3,824,134	\$4,127,040
Heating/Cooling Controls	158.90 %	\$2,059,401	\$1,296,000
Electrical Service and Distribution	99.85 %	\$929,817	\$931,200
Lighting	45.67 %	\$1,520,520	\$3,329,280
Communications and Security (Cameras, Pa System and Fire Alarm)	51.64 %	\$643,979	\$1,247,040

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.