2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Bethune School

Governance DISTRICT Report Type Elementarymiddle

Address 3301 Old York Rd. Enrollment 743
Philadelphia, Pa 19140 Grade Range '00-08'

Phone/Fax215-227-4433 / 215-227-8658Admissions CategoryNeighborhoodWebsiteWww.Philasd.Org/Schools/BethuneTurnaround ModelN/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	Cost of Assess	ed Deficiencies			
raciiit	y condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
	•	Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	34.44%	\$17,941,230	\$52,092,330
Building	35.31 %	\$17,683,145	\$50,085,981
Grounds	12.86 %	\$258,086	\$2,006,349

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	90.09 %	\$2,023,709	\$2,246,330
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.62 %	\$22,565	\$3,662,948
Windows (Shows functionality of exterior windows)	25.41 %	\$454,153	\$1,787,312
Exterior Doors (Shows condition of exterior doors)	36.42 %	\$52,405	\$143,898
Interior Doors (Classroom doors)	89.02 %	\$310,088	\$348,332
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,543,182
Plumbing Fixtures	37.78 %	\$506,960	\$1,341,725
Boilers	00.00 %	\$0	\$1,852,811
Chillers/Cooling Towers	44.78 %	\$1,087,914	\$2,429,395
Radiators/Unit Ventilators/HVAC	116.63 %	\$4,975,750	\$4,266,328
Heating/Cooling Controls	159.19 %	\$2,132,767	\$1,339,740
Electrical Service and Distribution	85.52 %	\$823,281	\$962,628
Lighting	34.83 %	\$1,198,635	\$3,441,643
Communications and Security (Cameras, Pa System and Fire Alarm)	47.99 %	\$618,640	\$1,289,128

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.