### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

# **Heston School**

Governance DISTRICT Report Type Elementarymiddle

 Address
 1621 N. 54Th St.
 Enrollment
 537

 Philadelphia, Pa 19131
 Grade Range
 '00-08'

Phone/Fax 215-581-5514 / 215-581-5724 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Heston Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	32.47%	\$14,155,935	\$43,602,229
Building	33.43 %	\$13,760,728	\$41,168,503
Grounds	16.27 %	\$395,207	\$2,428,828

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,571,169
Exterior Walls (Shows condition of the structural condition of the exterior facade)	05.62 %	\$169,290	\$3,013,332
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$1,470,336
Exterior Doors (Shows condition of exterior doors)	129.94 %	\$153,826	\$118,378
Interior Doors (Classroom doors)	67.89 %	\$194,542	\$286,556
Interior Walls (Paint and Finishes)	42.18 %	\$677,388	\$1,605,859
Plumbing Fixtures	17.90 %	\$197,531	\$1,103,773
Boilers	51.62 %	\$786,845	\$1,524,219
Chillers/Cooling Towers	33.17 %	\$662,897	\$1,998,547
Radiators/Unit Ventilators/HVAC	94.87 %	\$3,329,811	\$3,509,704
Heating/Cooling Controls	158.90 %	\$1,751,346	\$1,102,140
Electrical Service and Distribution	108.77 %	\$861,329	\$791,908
Lighting	27.51 %	\$778,752	\$2,831,275
Communications and Security (Cameras, Pa System and Fire Alarm)	26.26 %	\$278,450	\$1,060,504

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.