### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Palumbo School**

Governance DISTRICT Report Type High Address 1100 Catharine St. Enrollment 901 Philadelphia, Pa 19147 Grade Range '09-12'

Phone/Fax 215-351-7618 / 215-351-7685 Admissions Category Special Admit

Website Www.Philasd.Org/Schools/Palumbo Turnaround Model N/A

# **Building/System FCI Tiers**

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

# **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	11.08%	\$10,750,253	\$97,005,991
Building	11.03 %	\$10,688,936	\$96,880,618
Grounds	58.96 %	\$73,921	\$125,373

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	33.13 %	\$499,712	\$1,508,473
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.43 %	\$34,070	\$8,000,899
Windows (Shows functionality of exterior windows)	54.45 %	\$2,775,379	\$5,096,869
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$214,839
Interior Doors (Classroom doors)	00.00 %	\$0	\$696,375
Interior Walls (Paint and Finishes)	18.40 %	\$539,726	\$2,933,663
Plumbing Fixtures	12.72 %	\$318,476	\$2,503,985
Boilers	00.00 %	\$0	\$3,457,796
Chillers/Cooling Towers	47.32 %	\$2,145,464	\$4,533,843
Radiators/Unit Ventilators/HVAC	05.32 %	\$423,719	\$7,962,006
Heating/Cooling Controls	00.00 %	\$0	\$2,500,281
Electrical Service and Distribution	39.96 %	\$717,939	\$1,796,498
Lighting	03.86 %	\$248,039	\$6,422,944
Communications and Security (Cameras, Pa System and Fire Alarm)	07.03 %	\$169,135	\$2,405,826

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.