### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Moore School**

Governance DISTRICT Report Type Elementary Address 6900 Summerdale Ave. Enrollment 1184 Grade Range '00-05' Philadelphia, Pa 19111 215-728-5011 / 215-728-5692 Phone/Fax **Admissions Category** Neighborhood

Website Www.Philasd.Org/Schools/Moore Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)		ed Deficiencies			
raciiit	y Condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	45.32%	\$17,474,384	\$38,556,590
Building	46.42 %	\$17,390,769	\$37,467,886
Grounds	02.38 %	\$83,615	\$3,510,956

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	87.82 %	\$1,067,053	\$1,215,100
Exterior Walls (Shows condition of the structural condition of the exterior facade)	04.58 %	\$96,868	\$2,113,625
Windows (Shows functionality of exterior windows)	144.67 %	\$1,334,939	\$922,765
Exterior Doors (Shows condition of exterior doors)	96.66 %	\$109,288	\$113,061
Interior Doors (Classroom doors)	149.93 %	\$381,647	\$254,556
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$894,330
Plumbing Fixtures	02.05 %	\$43,809	\$2,137,998
Boilers	02.11 %	\$26,678	\$1,263,978
Chillers/Cooling Towers	65.60 %	\$1,087,247	\$1,657,320
Radiators/Unit Ventilators/HVAC	145.91 %	\$4,246,754	\$2,910,466
Heating/Cooling Controls	158.90 %	\$1,452,329	\$913,964
Electrical Service and Distribution	149.14 %	\$979,398	\$656,700
Lighting	54.43 %	\$1,278,033	\$2,347,871
Communications and Security (Cameras, Pa System and Fire Alarm)	69.99 %	\$615,509	\$879,436

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Moore PEC School**

Governance DISTRICT Report Type Elementary

Address 6900 Summerdale Ave. Enrollment Grade Range Philadelphia, Pa 19111

'00-05' 215-728-5011 / 215-728-5692 Phone/Fax **Admissions Category** Neighborhood

Website Www.Philasd.Org/Schools/Moore Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies						
Replacement Value						
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
	Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	01.21%	\$194,747	\$16,113,648
Building	00.88 %	\$111,132	\$12,602,692
Grounds	02.38 %	\$83,615	\$3,510,956

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$891,808
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$724,304
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$316,216
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$38,744
Interior Doors (Classroom doors)	00.00 %	\$0	\$87,232
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$272,616
Plumbing Fixtures	00.00 %	\$0	\$732,656
Boilers	00.00 %	\$0	\$433,144
Chillers/Cooling Towers	00.00 %	\$0	\$567,936
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$997,368
Heating/Cooling Controls	00.00 %	\$0	\$313,200
Electrical Service and Distribution	00.00 %	\$0	\$225,040
Lighting	02.06 %	\$16,592	\$804,576
Communications and Security (Cameras, Pa System and Fire Alarm)	00.92 %	\$2,775	\$301,368

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.