2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Conwell School

Governance DISTRICT Report Type Middle
Address 1849 E. Clearfield St. Enrollment 408
Philadelphia, Pa 19134 Grade Range '05-08'

Phone/Fax 215-291-4722 / 215-291-5019 Admissions Category Special Admit

N/A

Website Www.Philasd.Org/Schools/Conwell Turnaround Model

Building/System FCI Tiers

Facilit	v Candition Inday (FCI)	_ Cost of Assess	ed Deficiencies			
Facility Condition Index (FCI) = Replacem			nent Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
	Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	56.72%	\$15,601,608	\$27,507,120
Building	53.26 %	\$15,073,285	\$28,299,720
Grounds	108.82 %	\$528,323	\$485,520

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	88.64 %	\$623,429	\$703,331
Exterior Walls (Shows condition of the structural condition of the exterior facade)	30.24 %	\$736,200	\$2,434,168
Windows (Shows functionality of exterior windows)	187.43 %	\$2,230,169	\$1,189,840
Exterior Doors (Shows condition of exterior doors)	158.15 %	\$127,502	\$80,620
Interior Doors (Classroom doors)	32.23 %	\$62,892	\$195,156
Interior Walls (Paint and Finishes)	22.87 %	\$213,790	\$934,636
Plumbing Fixtures	08.48 %	\$63,708	\$751,712
Boilers	93.12 %	\$966,605	\$1,038,052
Chillers/Cooling Towers	63.79 %	\$868,291	\$1,361,088
Radiators/Unit Ventilators/HVAC	138.02 %	\$3,298,901	\$2,390,244
Heating/Cooling Controls	158.90 %	\$1,192,734	\$750,600
Electrical Service and Distribution	77.62 %	\$418,636	\$539,320
Lighting	51.94 %	\$1,001,478	\$1,928,208
Communications and Security (Cameras, Pa System and Fire Alarm)	55.64 %	\$401,860	\$722,244

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Conwell Annex School

Phone/Fax

Governance DISTRICT Report Type Middle

Address 3072 Emerald St Enrollment

Philadelphia, Pa 19134 Grade Range '05-08' 215-291-4722 / 215-291-5019 Admissions Category Special Admit

Website Www.Philasd.Org/Schools/Conwell Turnaround Model N/A

Building/System FCI Tiers

Cost of Assessed Deficiencies						
Facility Condition Index (FCI) = Replacement Value						
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
	Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	30.10%	\$9,128,293	\$30,326,594
Building	28.67 %	\$9,089,321	\$31,700,707
Grounds	01.73 %	\$38,973	\$2,255,059

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$2,046,640
Exterior Walls (Shows condition of the structural condition of the exterior facade)	33.86 %	\$548,921	\$1,621,317
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$707,833
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$86,726
Interior Doors (Classroom doors)	08.84 %	\$17,254	\$195,264
Interior Walls (Paint and Finishes)	66.69 %	\$457,482	\$686,022
Plumbing Fixtures	00.92 %	\$15,158	\$1,640,013
Boilers	22.97 %	\$222,666	\$969,570
Chillers/Cooling Towers	36.36 %	\$462,209	\$1,271,295
Radiators/Unit Ventilators/HVAC	97.71 %	\$2,181,497	\$2,232,557
Heating/Cooling Controls	82.62 %	\$579,206	\$701,082
Electrical Service and Distribution	180.63 %	\$909,901	\$503,740
Lighting	50.58 %	\$911,009	\$1,801,002
Communications and Security (Cameras, Pa System and Fire Alarm)	83.55 %	\$563,626	\$674,597

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.