2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Mastbaum School

Governance DISTRICT Report Type High Address 3116 Frankford Ave. Enrollment 746 '09-12' Grade Range Philadelphia, Pa 19134 Phone/Fax 215-291-4703 / 215-291-5657 Admissions Category Citywide Website Www.Philasd.Org/Schools/Mastbaum Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	11.83%	\$14,572,165	\$123,190,539
Building	11.76 %	\$14,396,327	\$122,366,220
Grounds	21.33 %	\$175,838	\$824,319

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,920,920
Exterior Walls (Shows condition of the structural condition of the exterior facade)	09.99 %	\$807,237	\$8,079,760
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$3,012,230
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$369,070
Interior Doors (Classroom doors)	137.79 %	\$1,144,941	\$830,960
Interior Walls (Paint and Finishes)	41.15 %	\$1,027,081	\$2,496,210
Plumbing Fixtures	00.00 %	\$0	\$6,979,180
Boilers	07.37 %	\$304,183	\$4,126,070
Chillers/Cooling Towers	22.26 %	\$1,204,455	\$5,410,080
Radiators/Unit Ventilators/HVAC	14.90 %	\$1,415,385	\$9,500,790
Heating/Cooling Controls	00.00 %	\$0	\$2,983,500
Electrical Service and Distribution	00.90 %	\$25,098	\$2,782,390
Lighting	22.58 %	\$1,730,238	\$7,664,280
Communications and Security (Cameras, Pa System and Fire Alarm)	07.71 %	\$221,400	\$2,870,790

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.