2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Rush School

Governance DISTRICT Report Type High
Address 11081 Knights Rd. Enrollment 606
Philadelphia, Pa 19154 Grade Range '09-12'

Phone/Fax 215-281-2603 / 215-281-2674 Admissions Category Special Admit

Website Http://Rushartsonline.Org Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	Cost of Assess	ed Deficiencies		
raciiit	y condition index (FCI)		Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%	
Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.	
	•	Systems			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program	

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	04.79%	\$5,324,450	\$111,181,490
Building	04.79 %	\$4,497,895	\$93,848,331
Grounds	04.77 %	\$826,554	\$17,333,159

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$4,561,056
Exterior Walls (Shows condition of the structural condition of the exterior facade)	06.66 %	\$499,055	\$7,497,360
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$4,776,096
Exterior Doors (Shows condition of exterior doors)	05.12 %	\$10,298	\$201,318
Interior Doors (Classroom doors)	02.89 %	\$18,858	\$652,548
Interior Walls (Paint and Finishes)	01.25 %	\$28,750	\$2,292,596
Plumbing Fixtures	00.00 %	\$0	\$2,346,396
Boilers	15.74 %	\$509,890	\$3,240,179
Chillers/Cooling Towers	54.33 %	\$2,308,102	\$4,248,504
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$7,460,915
Heating/Cooling Controls	00.00 %	\$0	\$2,342,925
Electrical Service and Distribution	00.00 %	\$0	\$1,683,435
Lighting	00.00 %	\$0	\$6,018,714
Communications and Security (Cameras, Pa System and Fire Alarm)	00.83 %	\$18,773	\$2,254,415

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Rush Annex School

Governance DISTRICT Report Type High

Address 11081 Knights Rd. Enrollment

 Philadelphia, Pa 19154
 Grade Range
 '09-12'

 215-281-2603 / 215-281-2674
 Admissions Category
 Special Admit

Phone/Fax 215-281-2603 / 215-281-2674 Admissions Category Special Ad Website Http://Rushartsonline.Org Turnaround Model N/A

Building/System FCI Tiers

Facility	v Condition Indox (ECI)	_ Cost of Assess	ed Deficiencies			
Facility Condition Index (FCI) = Replacement Value						
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
	Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	07.75%	\$1,973,311	\$25,453,336
Building	14.09 %	\$1,146,757	\$8,141,012
Grounds	04.77 %	\$826,554	\$17,333,159

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$532,202
Exterior Walls (Shows condition of the structural condition of the exterior facade)	07.48 %	\$32,347	\$432,241
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$188,707
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$23,121
Interior Doors (Classroom doors)	00.00 %	\$0	\$52,057
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$182,892
Plumbing Fixtures	01.80 %	\$7,865	\$437,225
Boilers	00.00 %	\$0	\$258,486
Chillers/Cooling Towers	00.00 %	\$0	\$338,926
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$595,197
Heating/Cooling Controls	172.16 %	\$321,781	\$186,908
Electrical Service and Distribution	00.00 %	\$0	\$134,297
Lighting	00.00 %	\$0	\$480,145
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$179,847

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.