## **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### Brown, JH School

Governance DISTRICT Report Type Elementary
Address 3600 Stanwood St. Enrollment 581
Philadelphia, Pa 19136 Grade Range '00-06'

Phone/Fax215-335-5650 / 215-335-5381Admissions CategoryNeighborhoodWebsiteWww.Philasd.Org/Schools/JhbrownTurnaround ModelN/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	Cost of Assess	ed Deficiencies			
raciiit	y condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
	•	Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	48.80%	\$14,485,645	\$29,683,179
Building	50.29 %	\$14,195,716	\$28,226,719
Grounds	18.91 %	\$289,929	\$1,533,479

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	75.75 %	\$592,935	\$782,798
Exterior Walls (Shows condition of the structural condition of the exterior facade)	05.18 %	\$104,349	\$2,016,135
Windows (Shows functionality of exterior windows)	116.98 %	\$1,150,815	\$983,760
Exterior Doors (Shows condition of exterior doors)	52.93 %	\$41,924	\$79,203
Interior Doors (Classroom doors)	135.58 %	\$259,949	\$191,727
Interior Walls (Paint and Finishes)	30.94 %	\$267,717	\$865,228
Plumbing Fixtures	32.78 %	\$242,086	\$738,503
Boilers	101.87 %	\$1,038,883	\$1,019,811
Chillers/Cooling Towers	65.60 %	\$877,209	\$1,337,171
Radiators/Unit Ventilators/HVAC	143.33 %	\$3,365,637	\$2,348,243
Heating/Cooling Controls	218.18 %	\$1,608,907	\$737,411
Electrical Service and Distribution	99.35 %	\$526,376	\$529,843
Lighting	46.03 %	\$871,962	\$1,894,326
Communications and Security (Cameras, Pa System and Fire Alarm)	50.00 %	\$354,811	\$709,553

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.